



State of Utah

JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

Department of
Environmental Quality

Richard W. Sprott
Executive Director

DIVISION OF SOLID AND
HAZARDOUS WASTE
Dennis R. Downs
Director

October 13, 2008

Ron Bird, Chairman
Beaver County Special Service District #5
P.O. Box 278
Milford, Utah 84751-0278

Subject: Inspection of the Beaver County Special Service District #5 Class I
Landfill on October 2, 2008

Dear Mr. Bird:

On October 2, 2008, Rob Powers with the Solid Waste Section conducted an unannounced inspection of the Beaver County Class I Landfill. The purpose of the inspection was to determine compliance with the **Utah Solid Waste Permitting and Management Rules** and the landfill permit. Enclosed is a copy of the inspection checklist and copies of the photographs taken during the inspection. The facility was found to be in very good shape and no violations were noted in the areas inspected.

The Division has a long history of a good working relationship with Beaver County and is looking forward to continuing that relationship. If you have any questions, please feel free to contact Rob Powers with the solid waste section at 801-538-6170 or by e-mail at rdpowers@utah.gov.

Sincerely,

Original Document signed by Dennis R. Downs on 10/13/08

Dennis R. Downs, Executive Secretary
Utah Solid and Hazardous Waste Control Board

DRD/rdp/kk

Enclosure: [Inspection Checklist](#), [Inspection Photographs](#)

c: David Blodgett, M.D., Health Officer/Director, Southwest Utah Health Department
John Chartier, District Engineer
Mike Neilson, Landfill Manager, Beaver County SSD #5

Beaver County Class I landfill inspection report Oct 2008.DOC

288 North 1460 West • Salt Lake City, UT
Mailing Address: P.O. Box 144880 • Salt Lake City, UT 84114-4880
Telephone (801) 538-6170 • Fax (801) 538-6715 • T.D.D. (801) 536-4414
www.deq.utah.gov
Printed on 100% recycled paper

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name	Beaver County Class I Landfill	County	Beaver
Location			
Inspection Date	10/2/08	Time In	11:00 am
		Time Out	Noon
Routine Oversight	<input checked="" type="checkbox"/>	Follow up	<input type="checkbox"/>
		Monitoring Evaluation	<input type="checkbox"/>
Facility Status	<input type="checkbox"/>	Construction Review	<input type="checkbox"/>
Announced	<input checked="" type="checkbox"/>	Unannounced	<input type="checkbox"/>
Weather Conditions	Sunny and very windy		
Inspection Goal	Compliance with the State Solid Waste Rules and there Permit		
Facility Contact	Mike Neilson		
Participants			
FOLLOW UP INSPECTION NEEDED	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Recommended Follow Up Date

(X - indicates items reviewed)

1. PRE-INSPECTION REVIEW

<input checked="" type="checkbox"/>	1.1 Permit Review
<input type="checkbox"/>	1.2 Annual Report Review
<input type="checkbox"/>	1.3 Previous Inspection Review
<input checked="" type="checkbox"/>	1.4 Facility Contacts Confirmed
This was an unannounced visit.	
<input type="checkbox"/>	1.5 Facility Contacted (if announced inspection)
<input checked="" type="checkbox"/>	1.6 Local Heath Contacted
No one from the local health department participated	
<input type="checkbox"/>	1.7 Other

<input type="checkbox"/>	2.14 Other
--------------------------	------------

3. SIGNS REQUIRED / PROPERLY POSTED

<input checked="" type="checkbox"/>	3.1 Operating Days / Hrs.
ok	
<input type="checkbox"/>	3.2 Directions & Procedure
<input type="checkbox"/>	3.3 Emergency Numbers
<input checked="" type="checkbox"/>	3.4 List of Unacceptable Materials
Ok	
<input type="checkbox"/>	3.5 Other

2. FACILITY / OPERATIONAL CONTROLS

<input checked="" type="checkbox"/>	2.1 Litter
Looked good, the wind was not blowing	
<input checked="" type="checkbox"/>	2.2 Roads
In good shape, not dusty.	
<input checked="" type="checkbox"/>	2.3 Gate House Operations
See photos	
<input checked="" type="checkbox"/>	2.4 Vectors
<input type="checkbox"/>	2.5 Communications
<input checked="" type="checkbox"/>	2.6 Recycling Area
See attached photos	
<input checked="" type="checkbox"/>	2.7 Fugitive Dust Control
In good shape.	
<input type="checkbox"/>	2.8 Waste Inspection Area
<input checked="" type="checkbox"/>	2.9 Scavenging Control
Not allowed.	
<input checked="" type="checkbox"/>	2.10 Open Burning
Not allowed	
<input checked="" type="checkbox"/>	2.11 Fences, Gates, Locks, Access Control
See attached photos.	
<input checked="" type="checkbox"/>	2.12 Working Face
See attached photos.	
<input type="checkbox"/>	2.13 Leachate Collection System

4. OPERATOR / REPRESENTATIVE / EMPLOYEES

<input checked="" type="checkbox"/>	4.1 On-site while open
<input checked="" type="checkbox"/>	4.2 Training
I recommended that Mike try and attend some of the SWANA training when he had the opportunity.	
<input type="checkbox"/>	4.3 Other

5. MONITORING

<input type="checkbox"/>	5.1 Methane
<input type="checkbox"/>	5.2 Random Inspections
<input type="checkbox"/>	5.3 Leachate
<input type="checkbox"/>	5.4 Ground Water
<input type="checkbox"/>	5.5 Other

6. DRAINAGE / EROSION

<input checked="" type="checkbox"/>	6.1 Water Run-on
Ok	

SOLID WASTE FACILITY INSPECTION REPORT

Date: 10/2/08

Facility Name: Beaver County Class I Landfill

<input checked="" type="checkbox"/>	6.2 Water Run-off
Ok	
<input type="checkbox"/>	6.3 Other

7. PROPER STORAGE / ISOLATION / DISPOSAL

<input type="checkbox"/>	7.1 Special Waste
<input checked="" type="checkbox"/>	7.2 Batteries
Collect for recycle	
<input type="checkbox"/>	7.3 Hazardous Waste
<input type="checkbox"/>	7.4 Infectious Waste
<input type="checkbox"/>	7.5 Tires
<input checked="" type="checkbox"/>	7.6 Dead Animals
Have a pit for the animals. See attached photos.	
<input type="checkbox"/>	7.7 Asbestos
<input checked="" type="checkbox"/>	7.8 Bulky Waste
In good shape.	
<input type="checkbox"/>	7.9 Contaminated Soil
<input type="checkbox"/>	7.10 Ash
<input type="checkbox"/>	7.11 Sludge
<input type="checkbox"/>	7.12 Other

8. COVER

<input checked="" type="checkbox"/>	8.1 Daily - Soil
Looked Ok	
<input type="checkbox"/>	8.2 Daily - Alternative
<input type="checkbox"/>	8.3 Intermediate
<input type="checkbox"/>	8.4 Final
<input type="checkbox"/>	8.5 Vegetation
<input type="checkbox"/>	8.6 Other

9. INSPECTION RECORDS

<input checked="" type="checkbox"/>	9.1 Random Inspection Report
Discussed what paper work to have on hand when I come to visit. I plan on a more extensive review on my next site visit.	
<input type="checkbox"/>	9.2 Gas Monitoring System
<input type="checkbox"/>	9.3 Surface Drainage Control
<input checked="" type="checkbox"/>	9.4 Daily Records
I did a very breif over view of the records and asked questions about his record keeping.	
<input checked="" type="checkbox"/>	9.5 Weight or Volumes
Had good records of this info that is put into a computer data base at the bulky waste site in Milford.	

<input type="checkbox"/>	9.6 Intermediate Cover
<input type="checkbox"/>	9.7 Final Cover
<input type="checkbox"/>	9.8 Self Inspection (Quarterly) Reports
<input type="checkbox"/>	9.9 Deviation from Plans
<input type="checkbox"/>	9.10 Permit, Permit Application and Rules Available
<input type="checkbox"/>	9.11 Other

10. MONITORING / SAMPLING / ANALYSIS RECORDS

<input type="checkbox"/>	10.1 Explosive Gas Monitoring
<input type="checkbox"/>	10.2 Leachate Sampling & Treatment
<input type="checkbox"/>	10.3 Ground Water Sampling Results
<input type="checkbox"/>	10.4 Other

11. SPECIAL WASTE RECORDS

<input type="checkbox"/>	11.1 Lab Analysis Results
<input type="checkbox"/>	11.2 Manifests
<input type="checkbox"/>	11.3 Treatment Certification
<input type="checkbox"/>	11.4 Paint Filter Test Results
<input type="checkbox"/>	11.5 Onsite Treatment Documentation
<input type="checkbox"/>	11.6 Other

12. SPECIAL PERMIT REQUIREMENTS

<input type="checkbox"/>	12.1
<input type="checkbox"/>	12.2
<input type="checkbox"/>	12.3

13. OTHER ITEMS

<input type="checkbox"/>	13.1 Notice of Inspections Form Completed and Signed
<input type="checkbox"/>	13.2
<input type="checkbox"/>	13.3
<input type="checkbox"/>	13.4
<input type="checkbox"/>	13.5

DSHW Inspector Signature: _____

SOLID WASTE FACILITY INSPECTION REPORT

Date: 10/2/08

Facility Name: Beaver County Class I Landfill

DSHW Inspector Name (type or print): Rob Powers

Date: 10/2/08



Scale at the Beaver County Landfill



Litter fence at the Beaver County Landfill



Working face



Green waste pile



Scrap metal pile



C & D waste cell